

---

## Executive Summary of Sampling and Analysis:

### Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Highland Elementary	5/28/2021	58	48	10	N/A	N/A

\*\* Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

### Listing of Outlets Requiring Remediation

#### Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
109.3-7	Room 124	Sink	24.4
109.3-13	Room 134 Main Sink	Sink	18.0
109.3-15	Room 134 Bathroom	Sink	24.5
109.3-37	Room 140 Sink	Sink	66.9
109.3-43	Room 141 Library Sink	Sink	28.6
109.3-56	Room 102 Sink	Sink	20.6
109.3-66	Room 113 Sink	Sink	17.2
109.3-69	Near Room 106 Boys Lav	Sink	16.2
109.3-75	Room 11A Sink	Sink	15.2
109.3-77	Room 111 Sink	Sink	23.0