
Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Lake Shore High School	2/25/2020 & 2/26/2020	128	122	6	N/A	N/A

** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
2020L-109.1-40	Classroom 119	Sink	32.3 ppb
2020L-109.1-44	Bathroom 124	Sink	17.7 ppb
2020L-109.1-50	Pool Drinking Fountain	Drinking Fountain	65.5 ppb
2020L-109.1-62	Storage Room 135	Sink	38.9 ppb
2020L-109.1-120	Science Room 222	Sink	113 ppb
2020L-109.1-211	Faculty Women Bathroom 243	Sink	22.6 ppb