
Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
WT Hoag Elementary	5/27/2021	42	32	10	N/A	N/A

** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
109.6-9	Room 103 Bathroom	Sink	19.9
109.6-17	Room 108	Sink	24.7
109.6-21	Room 110	Sink	33.0
109.6-23	Room 109	Sink	62.8
109.6-27	Room 112 Media/Copy	Sink	53.2
109.6-46	Room 116	Sink	25.1
109.6-47	Room 119	Sink	31.7
109.6-54	Kitchen Left Triple	Sink	160
109.6-55	Kitchen Right Triple	Sink	369
109.6-58	Annex 154	Sink	20.8